

GREAT WESTERN RAILWAY STATIONS

PART 7 South Wales Railway and Branches

LENS OF SUTTON ASSOCIATION
List 29 (Issue 1 November 2013)



Quakers Yard 1955 (66365)

THE SOUTH WALES RAILWAY

The original South Wales Railway extended from Grange Court to Milford Haven though, in later years, "the South Wales main line" was generally regarded as a line from Gloucester to Fishguard. The following list of station photographs from the Lens of Sutton collection includes images from the SWR main line and from connecting routes such as the Cinderford branch and the Pembroke & Tenby line. The list also includes part of the Newport, Abergavenny & Hereford route and various connecting branch lines in South Wales and elsewhere in the Welsh border areas.

- 57408 GWR Abbey Dore Post-closure view, circa 1970, showing derelict facilities.
- 57418 GWR Abbeystead General view, circa 1930, showing the single platform and station building, looking towards Pontrilas.
- 52940 GWR Aberayron Detailed view showing '14XX' class 0-4-2T No.1452 outside the single-road locomotive shed.
- 57758 GWR Aberayron General view, circa 1960s, showing the single platform and station building, looking south towards Lampeter.
- 57759 GWR Aberayron Postcard view, circa 1912, showing the single platform terminus from the east.
- 57760 GWR Aberayron Postcard view, circa 1912, showing the station from the nearby hillside.
- 57761 GWR Aberayron Great Western staff group, posed on platform circa 1914.
- 57762 GWR Aberayron General view, circa 1960s, showing the single platform and station building, looking south towards Lampeter.
- 57763 GWR Aberayron Postcard view, circa 1912, showing a branch train departing from the terminus.
- 57764 GWR Aberayron Archive view, circa 1912, showing the single platform and station building with construction work still in progress.
- 57766 GWR Aberayron Archive view, circa 1911, showing the single platform terminus under construction.
- 57767 GWR Aberayron Postcard view, circa 1912, showing the station and goods yard from the nearby hillside.
- 57768 GWR Aberayron General view, circa 1930s, showing the single platform and station building, with unidentified '48XX' class 0-4-2T.
- 57769 GWR Aberayron Postcard view, circa 1920s, showing the station and goods yard from the nearby hillside.
- 57770 GWR Aberayron General view, circa 1960s, showing passenger station and goods sidings, looking north towards the terminal buffer stops.
- 57771 GWR Aberayron Postcard view, circa 1912, showing the south end of platform, with approaching train.
- 66070 GWR Aberayron General view, 26-8-48, looking back from platform end showing branch train awaiting departure
- 52811 GWR Aberbeeg Postcard view, circa 1920, showing the station and surrounding hillsides.
- 52812 GWR Aberbeeg General view, 12-05-1956, showing a '57XX' class 0-6-0PT heading a Gloucestershire Railway Society special.
- 52813 GWR Aberbeeg General view, circa 1960s, showing the platforms and station buildings, looking towards Newport.
- 52814 GWR Aberbeeg General view, circa 1960s, showing the platforms, road overbridge and station nameboard.
- 52815 GWR Aberbeeg General view, circa 1960s, showing the platforms, station buildings and footbridge.
- 52816 GWR Aberbeeg Postcard view, circa 1912, showing the platforms, station buildings and footbridge.
- 52817 GWR Aberbeeg General view, circa 1960s, showing the platforms and part of the station buildings.
- 52818 GWR Aberbeeg General view, circa 1960s, showing the platforms and station buildings.
- 52819 GWR Aberbeeg Postcard view, circa 1912, showing the railway and valley.
- 52820 GWR Aberbeeg Postcard view, circa 1912, showing the station and surrounding valley.
- 52821 GWR Aberbeeg General view, circa 1930s, showing the four-road locomotive shed.
- 52822 GWR Aberbeeg General view, circa 1960s, showing the platforms, part of the station building, and road overbridge.
- 52823 GWR Aberbeeg Postcard view, circa 1912, showing "Railway Sidings, Aberbeeg".
- 52824 GWR Aberbeeg General view, circa 1920s, showing the station and surrounding valley.

54319 GWR Aberbeeg A general view of the motive power depot, circa 1962.
52964 GWR Abercarn Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.
52965 GWR Abercarn Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.
52966 GWR Abercarn General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.
54327 GWR Abercarn General view, circa 1960s, showing the up and down platforms, part of the station building, and footbridge.
57827 GWR Aberdare A detailed view showing Aberdare North signal cabin.
57801 GWR Aberdylais Post-closure view, circa 1960s, showing the up and down platforms.
57802 GWR Aberdylais Post-closure view, circa 1960s, showing the up and down platforms.
54397 GWR Abergavenny Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.
57976 GWR Abergavenny General view, circa 1960s, showing the main up and down platforms and station buildings.
57977 GWR Abergavenny Postcard view, circa 1912, showing the up and down platforms, with an unidentified 4-4-0.
54398 GWR Abergavenny (Monmouth Road) Platform view, circa 1960s.
57978 GWR Abergavenny Junction Post-closure view, showing derelict facilities, circa 1968.
52870 GWR Abergwynfi Post-closure view, circa 1966, showing derelict facilities.
52871 GWR Abergwynfi General view, circa 1960s, showing the single platform and station building, with '45XX' class 2-6-2T No.5555.
52872 GWR Abergwynfi General view, circa 1960s, showing the single platform and station building, with '45XX' class 2-6-2T alongside.
52967 GWR Abernant Post-closure view, circa 1960s, showing derelict facilities.
52968 GWR Abernant Post-closure view, circa 1960s, showing derelict facilities.
52827 GWR Abertillery Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.
52828 GWR Abertillery General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.
52829 GWR Abertillery Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.
52830 GWR Abertillery Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.
52831 GWR Abertillery Postcard view, circa 1912, showing "Oak Street and station, Abertillery".
52832 GWR Abertillery General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.
52969 GWR Alltddu Halt General view, circa 1960s, showing the single platform and waiting shelter.
57799 GWR Alltdu Halt General view, circa 1960s, showing the single platform and waiting shelter.
54358 GWR Ammanford & Tirydail Detailed view, circa 1960s, showing Tirydail signal cabin.
57909 GWR Ammanford & Tirydail General view, circa 1960s, showing the single platform, station buildings and signal box.
57910 GWR Ammanford & Tirydail General view, circa 1960, showing the single platform and station building.
57911 GWR Ammanford & Tirydail General view, circa 1960, showing the single platform and station building.
57912 GWR Ammanford & Tirydail General view, circa 1960s, showing the platform and station building.
57931 GWR Ammanford & Tirydail General view, circa 1962, showing the single platform, station building and signal box.
57940 GWR Ammanford & Tirydail A detailed view, showing the signal cabin, circa 1962.
57932 GWR Ammanford Colliery Halt General view, circa 1960s, showing the single platform.
57990 GWR Ammanford Colliery Halt Detailed view, circa 1962, showing Ammanford Colliery Siding signal cabin.
52951 GWR Awre General view, circa 1960s, showing the up and down platforms, station buildings and level crossing.

57454 GWR Awre General view, circa 1960s, showing the up and down platforms.

57455 GWR Awre Archive view, circa 1905, showing the up and down platforms, station buildings and signal box.

57406 GWR Bacton Post-closure view, circa 1970, showing derelict facilities.

57411 GWR Bacton Post-closure view, circa 1970, showing derelict facilities.

57416 GWR Bacton General view, circa 1930, showing the single platform and station building.

52859 GWR Bassaleg Post-closure view, circa 1960s, showing derelict facilities.

52860 GWR Bassaleg Post-closure view, circa 1960s, showing derelict facilities.

52861 GWR Bassaleg Detailed view showing signal cabin, circa 1960s.

51848 GWR Beavers Hill Halt General view, circa 1960s, showing short wooden platform and dead straight track.

51849 GWR Beavers Hill Halt General view, circa 1960s, showing the level crossing.

51982 GWR Beavers Hill Halt General view, circa 1960s, showing the single platform and level crossing.

57697 GWR Beavers Hill General view, circa 1960s, showing the single platform, looking west towards Pembroke Dock.

54516 RHYM/GWR Bedlinog General view, circa 1930s, showing the up and down platforms and road overbridge.

54826 RHYM/GWR Bedlinog General view, circa 1960s, showing derelict facilities.

52917 GWR Blackmill Post-closure view, circa 1960s, showing derelict facilities.

52918 GWR Blackmill Post-closure view, circa 1960s, showing derelict facilities.

52919 GWR Blackmill Post-closure view, circa 1960s, showing derelict facilities.

52920 GWR Blackmill Postcard view, circa 1912, showing the platform, signal box and station building.

52858 GWR Blaenavon Archive view, circa 1912, looking through station with train in platform and buildings to the left.

52954 GWR Blaenavon Postcard view, circa 1912, showing the up and down platforms and station buildings.

66377 GWR Blaenavon, General view of low level platforms, c1955, looking to station with pannier on passenger.

66378 GWR Blaenavon, General view of low level platforms, c1955, looking to station with pannier running around passenger train.

51861 GWR Blaengarw Platform end view, circa 1960s.

51862 GWR Blaengarw Post-closure view, circa 1960s, showing the derelict platform.

51864 GWR Blaengarw Post-closure view, circa 1960s, showing the derelict platform.

52902 GWR Blaengarw General view, circa 1960s, showing a railtour in the single platform station.

52903 GWR Blaengarw Postcard view, circa 1912, showing the single platform, station building and goods shed.

52904 GWR Blaengarw Postcard view, circa 1912, showing the single platform and station building.

52905 GWR Blaengarw Panoramic view, circa 1912, showing the station and the surrounding hillsides.

66473 GWR Blaengarw General view, circa 1953, showing single platform with pannier standing bunker first on passenger train.

57755 GWR Blaenplwyf Halt Post-closure view, circa 1960s, showing the single platform.

52833 GWR Blaina General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

52834 GWR Blaina General view, circa 1960s, showing the up and down platforms, footbridge, signal box and station buildings.

52835 GWR Blaina Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

52836 GWR Blaina Postcard view, circa 1912, showing the up and down platforms, signal box and footbridge.

51959 GWR Boncath General view, circa 1962, showing the up and down platforms and part of the station buildings, looking north towards the level crossing.

51960 GWR Boncath General view, circa 1962, showing the up platform and main station building, looking north towards the level crossing.

54324 GWR Bourneville Halt General view, circa 1960s, showing the up and down platforms.

52825 GWR Bourneville Halt General view, circa 1960s, showing the up and down platforms.

57530 GWR Bridgend Postcard view, circa 1912, showing the main up and down platforms, station buildings and footbridge.

57531 GWR Bridgend General view, circa 1960, looking along platforms 1 and 2 towards the standard GWR footbridge.

57532 GWR Bridgend Postcard view, circa 1905, showing double-headed GWR express in the main line platform and a Barry Railway service in the bay.

57556 GWR Bridgend Panoramic view, circa 1920, showing the platforms and station buildings.

57581 GWR Bridgend General view, circa 1960s, showing the main up and down platforms and part of the station buildings.

66140 GWR Bridgend General view, 9-51, looking to footbridge.

57537 GWR Briton Ferry Postcard view, circa 1912, showing the up and down platforms and station buildings.

57538 GWR Briton Ferry General view, circa 1963, showing the main up and down platforms.

57539 GWR Briton Ferry General view, circa 1963, showing the main up and down platforms, station buildings and footbridge.

57540 GWR Briton Ferry Archive view, circa 1900, showing the up and down platforms and station buildings.

52952 GWR Briton Ferry Road Postcard view, circa 1912, showing the up and down platforms and station buildings.

57777 GWR Bronwydd Arms General view, circa 1960s, showing the station building, signal box and level crossing.

57778 GWR Bronwydd Arms General view, circa 1960s, showing the single platform and station building.

57782 GWR Bryn Teify General view, circa 1960s, showing the single platform and station building.

57783 GWR Bryn Teify General view, circa 1960s, showing the single platform and station building.

57937 GWR Brynamman Post-closure view, showing derelict facilities.

57938 GWR Brynamman Post-closure view, showing derelict facilities.

57939 GWR Brynamman Postcard view, circa 1912, showing the single platform and station building.

66077 GWR Brynamman General view, 27-8-48, taken from track level looking to station with 11:15 am service from Llanelly in view.

52909 GWR Brynmenyn General view, circa 1960s, showing the platforms and station buildings.

52910 GWR Brynmenyn Postcard view, circa 1912, showing the platform s , signal box and station buildings.

52911 GWR Brynmenyn General view, circa 1960s, showing the platforms and station buildings.

52912 GWR Brynmenyn General view, circa 1960s, showing the platforms and station building.

52913 GWR Brynmenyn General view, circa 1960s, showing the platforms and station buildings with one track removed.

52914 GWR Brynmenyn General view, circa 1960s, showing the platforms and part of the station buildings.

52915 GWR Brynmenyn General view, circa 1960s, showing the platforms and station buildings.

52916 GWR Brynmenyn General view, circa 1960s, showing the platforms and station buildings, with railtour in station.

52953 GWR Burry Port Postcard view, circa 1912, showing the up and down platforms station buildings and footbridge.

57571 GWR Burry Port Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

57894 GWR Bynea General view, circa 1960s, showing the up and down platforms and station buildings.

57895 GWR Bynea General view, circa 1960s, showing the up and down platforms and part of the station buildings.

52877 GWR Caerau Postcard view, circa 1920, showing the "Station Square Caerau" (blurred).

52878 GWR Caerau General view, circa 1960s, showing the single platform and part of the station building.

52895 GWR Caerau General view, circa 1960s, showing the single platform and station building.

57985 GWR Caerleon View from bridge, circa 1912, showing the up and down platforms and a local passenger train.

57986 GWR Caerleon Post-closure view, showing derelict facilities from the road overbridge.

57987 GWR Caerleon Postcard view, circa 1912, showing the up and down platforms, station buildings and road bridge, with passenger train.

57988 GWR Caerleon Postcard view, circa 1906, showing a crowded platform with a 'Birdcage' 2-4-2T alongside.

57989 GWR Caerleon Postcard view, circa 1912, showing the up and down platforms, station buildings and road overbridge.

51954 GWR Caldicot Detailed view showing Caldicot Junction signal cabin, circa 1960s.

57469 GWR Caldicot General view, circa 1960, showing the up and down platforms and pagoda buildings.

57470 GWR Caldicot General view, circa 1960, showing the up and down platforms.

57867 GWR Caradog Falls Halt General view, circa 1960s, showing the single platform and waiting shelter, looking north towards Aberystwyth.

57509 GWR Cardiff Clarence Road General view, circa 1960, showing terminal platforms and station buildings.

57510 GWR Cardiff Clarence Road Detailed view of station buildings, circa 1968.

57563 GWR Cardiff Clarence Road General view of terminus, circa 1960, showing the platform and run-round loop.

57504 GWR Cardiff General General view, circa 1970, showing the platforms and station buildings.

57505 GWR Cardiff General General view, circa 1960s, showing the platforms and station buildings.

57506 GWR Cardiff General Panoramic view, circa 1912, showing the platforms and station buildings.

57507 GWR Cardiff General Postcard view, circa 1912, showing the platforms and station buildings.

57508 GWR Cardiff General Postcard view, looking along Platform One, circa 1912.

57512 GWR Cardiff General General view, circa 1960, showing the main up and down platforms and station buildings.

57513 GWR Cardiff General Detailed view, circa 1920s, showing "Cardiff Riverside" platforms, which were amalgamated with Cardiff General in 1940.

66543 GWR Cardiff General General view, 1951, showing curved island platform

51955 GWR Cardigan General view, circa 1962, showing the west end of the platform, looking towards the signal box.

51956 GWR Cardigan General view, circa 1962, showing the single platform and station building, looking east towards the buffer stops.

57721 GWR Cardigan General view, circa 1960s, showing the single platform, signal cabin and station buildings, looking west towards the terminal buffer stops.

57722 GWR Cardigan General view, circa 1960s, showing the single platform and station building, with '16XX' class 0-6-0PT No.1669.

57723 GWR Cardigan General view, circa 1960s, showing the single platform and station buildings, looking eastwards from the buffer stops.

57724 GWR Cardigan Postcard view, circa 1912, showing the single platform and station building, looking west towards the terminal buffer stops.

57725 GWR Cardigan Archive view, circa 1912, showing '850' class 0-6-0ST No.1982 (?) with a mixed train.

57726 GWR Cardigan General view, circa 1960s, showing an unidentified '16XX' class 0-6-0PT alongside the station building.

57727 GWR Cardigan General view, circa 1960s, showing the single platform, station building and goods shed, looking south towards Whitland.

57728 GWR Cardigan General view, circa 1960s, showing '45XX' class 2-6-2T No.4541 engaged in shunting operations.

57729 GWR Cardigan General view, circa 1950s, showing a '45XX' class 2-6-2T outside the locomotive shed.

57730 GWR Cardigan General view, circa 1960s, showing the single platform terminus, looking west towards the buffer stops.

57749 GWR Cardigan General view, circa 1960s, showing the single platform, signal cabin and goods yard, looking west towards the buffer stops.

64771 GWR Cardigan Detailed view of platform end looking to signal box with 2-6-2T in platform with train, c1950s.

66539 GWR Cardigan General view circa 1950s, showing platform and building looking to buffers with 4545 standing in platform on passenger service.

52960 GWR Cardonell Halt General view, circa 1920, showing the single platform.

57595 GWR Carmarthen Detailed view, showing interior of engine shed, with fitters, etc, assembled in front of locomotive.

57596 GWR Carmarthen General view, circa 1960, showing the Platform Two and the main station building, looking north.

57597 GWR Carmarthen Postcard view, circa 1912, showing the north end of station, looking towards Aberystwyth.

57598 GWR Carmarthen General view, circa 1960, showing the up and down platforms, looking south towards Carmarthen Junction.

57599 GWR Carmarthen General view, circa 1960, showing the up and down platforms, the 'middle road' and the station buildings, looking north.

57600 GWR Carmarthen General view, circa 1905, showing the up and down platforms, station buildings and footbridge, looking north.

57591 GWR Carmarthen Junction General view, circa 1920, showing the up and down platforms and station buildings.

57592 GWR Carmarthen Junction General view, circa 1960, showing derelict platform (closed 1926).

57593 GWR Carmarthen Junction General view, circa 1960, showing the derelict platform.

57594 GWR Carmarthen Junction General view, circa 1960, showing the derelict platform.

52995 GWR Celynen North Halt General view, circa 1960s, showing the island platform and waiting shelter.

52996 GWR Celynen North Halt General view, circa 1960s, showing the island platform and waiting shelter.

52997 GWR Celynen South Halt Post-closure view, circa 1960s, showing derelict platforms.

52998 GWR Celynen South Halt Post-closure view, circa 1960s, showing derelict platforms.

57367 GWR Chepstow General view, circa 1968, showing the up and down platforms and station buildings, with class '52' Co-Co in distance.

57463 GWR Chepstow Postcard view, circa 1912, showing the up and down platforms, footbridge and signal box, looking east towards Paddington.

57464 GWR Chepstow General view, 30-08-1953, showing the up and down platforms and station buildings, looking east towards Paddington.

57465 GWR Chepstow Detailed view, 30-08-1953, showing rear elevation of main station building.

57466 GWR Chepstow General view, circa 1960, showing the up and down platforms, station buildings and footbridge.

57467 GWR Chepstow General view, 30-08-1953, showing the up and down platforms, station buildings and footbridge.

57468 GWR Chepstow General view, 01-09-1953, showing the up and down platforms, station buildings and footbridge.

66381 GWR Chepstow Detailed view, c1955, showing 1421 standing under the bridge at the platform end with a Wye Valley service.

57750 GWR Ciliau Aeron General view, circa 1960s, showing the single platform and station building.

57754 GWR Ciliau Aeron General view, circa 1960s, showing the single platform and station building.

54390 GWR/MID Cinderford General view, circa 1960s, showing the single platform and station building.

66226 GWR/MID Cinderford General view, 7-9-49, showing single platform with auto train in platform.

51981 GWR Clarboston Road Postcard view, circa 1912, showing the up and down platforms, station buildings and road overbridge.

57621 GWR Clarboston Road General view, circa 1960, showing the up and down platforms and station buildings, looking east towards Paddington.

57622 GWR Clarboston Road General view, circa 1960, showing the up and down platforms and down station buildings, with '57XX' class 0-6-0PT No.3633 in bay platform.

57623 GWR Clarboston Road General view, circa 1960, showing the up and down platforms, looking west towards Fishguard.

57624 GWR Clarboston Road View from overbridge, circa 1960s, showing the up and down platforms and station buildings, looking west towards Fishguard.

57407 GWR Clifford Post-closure view, circa 1970, showing derelict facilities.

57616 GWR Clynderwen Postcard view, circa 1912, showing staggered up and down platforms, station buildings and goods shed.

57617 GWR Clynderwen Postcard view, circa 1912, showing the main station building.

57618 GWR Clynderwen General view, circa 1960, showing staggered platforms and goods yard.

57619 GWR Clynderwen Postcard view, circa 1912, showing staggered platforms, station buildings and goods shed.

57620 GWR Clynderwen General view, circa 1960, showing the up and down platforms and station buildings.

57803 GWR Clyne Halt Post-closure view, circa 1970, showing derelict facilities.

57804 GWR Clyne Halt Post-closure view, circa 1970, showing derelict facilities.

57553 GWR Cockett View from bridge, circa 1912, showing the up and down platforms and signal box.

57585 GWR Cockett View from top of cutting, circa 1914, showing the up and down platforms, station buildings and road overbridge.

66454 GWR Coleford Detailed view, 9-9-49, showing station building and signal box.

66537 GWR Coleford General view, 9-9-49, showing platform, station building and signal box.

66224 GWR/MID Coleford General view, 9-9-49, showing single platform with diesel railcar during visit of BLS railtour.

57787 GWR Conwil General view, circa 1960s, showing the up and down platforms and part of the station buildings.

57788 GWR Conwil General view, circa 1930s, showing the up and down platforms and part of the station buildings.

52961 GWR Copper Pit Halt General view, circa 1960s, showing the single platform and overbridge, looking towards Felin Fran.

57731 GWR Crmmych Arms Postcard view, circa 1906, showing the station filled with cattle wagons on a market day.

57732 GWR Crmmych Arms Postcard view, circa 1912, showing the up and down platforms, station buildings and goods yard.

57733 GWR Crmmych Arms Postcard view, circa 1912, showing the up and down platforms, station buildings and goods yard.

54317 GWR Crogen Halt General view, circa 1960s, showing the single platform.

54318 GWR Crogen Halt General view, circa 1960s, showing the single platform.

52862 GWR Cross Keys General view, circa 1962, showing the up and down platforms , station buildings and footbridge.

52863 GWR Cross Keys Post-closure view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

52864 GWR Cross Keys Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

52865 GWR Cross Keys Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

57850 GWR Crumlin High Level Postcard view, circa 1912, showing an unidentified '39XX' class 2-6-2T crossing Crumlin Viaduct.

57851 GWR Crumlin High Level Postcard view, circa 1912, showing up and down trains crossing on Crumlin Viaduct.

57852 GWR Crumlin High Level Postcard view, circa 1912, showing "Crumlin Viaduct Pontypool".

57853 GWR Crumlin High Level General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

57854 GWR Crumlin High Level Postcard view, circa 1912, showing the up and down platforms and distinctive, gothic-style station buildings.

57855 GWR Crumlin High Level General view, circa 1960s, showing the up and down platforms with viaduct in the distance.

57856 GWR Crumlin High Level Post-closure view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

57857 GWR Crumlin High Level Post-closure view, circa 1960s, showing the up and down platforms and station buildings, framed by footbridge.

52867 GWR Crumlin Low Level Postcard view, circa 1912, showing the up and down platforms and station buildings, with Crumlin Viaduct in the background.

52868 GWR Crumlin Low Level Post-closure view, circa 1960s, showing the up and down platforms, station buildings and signal box.

52869 GWR Crumlin Low Level Post-closure view, circa 1960s, showing the up and down platforms and station buildings.

51961 GWR Crymmych Arms General view, circa 1962, showing the up and down platforms and station building, with unidentified '45XX' class 2-6-2T on goods working.

51962 GWR Crymmych Arms General view, circa 1962, showing the up and down platforms and signal box, looking south.

51963 GWR Crymmych Arms General view, circa 1962, showing the up and down platforms and station buildings, looking south.

51964 GWR Crymmych Arms General view, circa 1962, showing the up and down platforms and station buildings, looking north towards Cardigan.

51965 GWR Crymmych Arms General view, circa 1962, showing the up and down platforms and part of the station buildings, with unidentified '45XX' class 2-6-2T approaching the station with a down freight train.

51966 GWR Crymmych Arms General view, circa 1962, showing the up and down platforms, station buildings and signal box, looking north towards Cardigan.

57991 GWR Cwm Postcard view, circa 1912, showing the up and down platforms and station buildings from the adjacent road overbridge.

57992 GWR Cwm Post-closure view, circa 1966, showing the up and down platforms and station buildings.

57993 GWR Cwm Post-closure view, circa 1966, showing the up and down platforms and station buildings.

54827 RHYM/GWR Cwm Bargoed General view, circa 1960s, showing derelict facilities.

57858 GWR Cwmbach Halt Post-closure view, circa 1960s, showing the up and down platforms with one track removed.

57979 GWR Cwmbran Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

57980 GWR Cwmbran Postcard view, circa 1912, showing the up and down platforms and station buildings.

57981 GWR Cwmbran Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

57982 GWR Cwmbran General view, showing new station, opened 12-05-1986.

57983 GWR Cwmbran Post-closure view, showing derelict facilities.

57984 GWR Cwmbran Postcard view, circa 1912, showing "The Railway Station, Cwmbran".

52866 GWR Cwmcarn Post-closure view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

54338 GWR Cwmcarn General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

57797 GWR Derry Ormond General view, circa 1960s, showing the single platform, station building and signal box, looking north towards Aberystwyth.

57798 GWR Derry Ormond General view, circa 1960s, showing the single platform and part of the station building, looking south towards Carmarthen.

57913 GWR/LNWR Derwydd Road Post-closure view, circa 1968, showing derelict facilities.

57914 GWR/LNWR Derwydd Road Post-closure view, circa 1968, showing derelict facilities.

57413 GWR Dorstone Postcard view, circa 1912, showing the single platform and station building, with approaching train.

66535 GWR Dowlais Central General view, 9-51, looking along single platform with pannier No. GW 9643 on 2 coach set in platform.

52711 RHYM/GWR Dowlais Cae Harris General view, circa 1960, showing the terminal platforms packed with empty coaching stock.

52714 RHYM/GWR Dowlais Cae Harris General view, circa 1960, showing '56XX' class 0-6-2T in terminus with passenger working.

54531 RHYM/GWR Dowlais Cae Harris General view looking north, circa 1950s, with '56XX' class 0-6-2T on passenger working.

54713 RHYM/GWR Dowlais Cae Harris Postcard view, circa 1912, showing the station from nearby hillside.

54829 RHYM/GWR Dowlais Cae Harris General view, circa 1960s, showing the platforms and station buildings.

54996 RHYM/GWR Dowlais Cae Harris General view, circa 1900, showing the platform and station buildings, looking towards the terminal buffer stops.

57382 RHYM/GWR Dowlais Cae Harris Panoramic view of engine shed, circa 1960.

52806 GWR Ebbw Vale General view, circa 1962, showing the single platform and part of the station building.

52801 GWR Ebbw Vale Postcard view, circa 1912, showing the single platform and station building from the overbridge.

52802 GWR Ebbw Vale Postcard view, circa 1912, showing the single platform and station building.

52803 GWR Ebbw Vale View from bridge, circa 1912, showing the single platform and station building, with branch passenger train.

52804 GWR Ebbw Vale Post-closure view, circa 1968, showing derelict facilities.

52805 GWR Ebbw Vale General view, circa 1962, showing the single platform and station building from the overbridge.

52807 GWR Ebbw Vale Post-closure view, circa 1968, showing derelict facilities.

52808 GWR Ebbw Vale Post-closure view, circa 1968, showing derelict facilities.

52809 GWR Ebbw Vale Postcard view, circa 1912, showing the single platform and station building.

52810 GWR Ebbw Vale Postcard view, circa 1912, showing the single platform and station building from the road overbridge.

57998 GWR Ebbw Vale General view, circa 1964, showing the single platform and station building from the overbridge.

57999 GWR Ebbw Vale General view, circa 1920, showing the single platform, station building and surrounding hillsides.

54331 GWR Ely General view, circa 1920s, showing the up and down platforms, station buildings and footbridge.

54332 GWR Ely General view, 23-08-1953, showing the up and down platforms, station buildings and footbridge.

57751 GWR Felin Fach General view, circa 1960s, showing the up and down platforms and station buildings.

57752 GWR Felin Fach General view, circa 1960s, showing the up and down platforms, station buildings and signal cabin.

57753 GWR Felin Fach General view, circa 1960s, showing the up and down platforms and part of the station buildings.

52729 GWR Felindyffryn Halt General view, circa 1960s, showing the single platform and station building.

52930 GWR Felindyffryn Halt General view, circa 1960s, showing the single platform and waiting shelter.

57586 GWR Ferryside General view, circa 1960s, showing the up and down platforms and goods shed.

57587 GWR Ferryside View from footbridge, circa 1912, showing the up and down platforms, station buildings and goods shed.

57588 GWR Ferryside Archive view, circa 1900, showing a GWR staff group on the platform.

57589 GWR Ferryside View from footbridge, circa 1963, showing the up and down platforms and station buildings.

57590 GWR Ferryside General view, circa 1960, showing the up and down platforms, station buildings and footbridge.

57632 GWR Fishguard & Goodwick General view, circa 1960, showing the up and down platforms, station buildings, signal box and road overbridge.

57633 GWR Fishguard & Goodwick General view, circa 1960, showing the up and down platforms, signal box and road overbridge.

57634 GWR Fishguard & Goodwick General view, circa 1960, showing the up and down platforms, with '14XX' class 0-4-2Ts Nos.1431 and 1452.

57635 GWR Fishguard & Goodwick Panoramic view, circa 1900, showing the station from the nearby hillside.

57636 GWR Fishguard & Goodwick View south from bridge, circa 1960s, showing the up and down platforms, station buildings and signal cabin, with unidentified '57XX' class 0-6-0PT.

57637 GWR Fishguard & Goodwick General view, circa 1960, showing the up and down platforms, station buildings, signal box and overbridge, looking north.

57638 GWR Fishguard & Goodwick General view, circa 1960, showing the up and down platforms, looking south towards Paddington.

57640 GWR Fishguard Harbour General view, circa 1950s, showing part of the station buildings.

57641 GWR Fishguard Harbour Internal view, circa 1960, looking along Platform Two.

57642 GWR Fishguard Harbour General view looking north, circa 1960s, showing the platforms and part of the station buildings.

57643 GWR Fishguard Harbour Postcard view, circa 1912, showing the platforms , station buildings and train shed.

57644 GWR Fishguard Harbour Postcard view, circa 1912, showing the station, quays and cattle pens.

57645 GWR Fishguard Harbour Platform view, circa 1920, looking north towards the terminal buffer stops.

57646 GWR Fishguard Harbour Postcard view, circa 1912, showing the platforms and train shed.

57647 GWR Fishguard Harbour Postcard view, circa 1912, showing the platforms and train shed.

57648 GWR Fishguard Harbour Archive view, circa 1907, showing the station and quays.

57649 GWR Fishguard Harbour Postcard view, circa 1912, showing the platforms and train shed.

54333 GWR Garnant General view, circa 1960s, showing the platforms , station buildings and signal cabin.

57933 GWR Garnant Postcard view, circa 1912, showing travellers on single platform with the station buildings visible in the background.

57934 GWR Garnant Post-closure view, showing the derelict facilities.

57935 GWR Garnant Post-closure view, showing the derelict facilities.

57936 GWR Garnant Postcard view, circa 1912, showing the single platform and station building.

54322 GWR Garneddwen Halt General view, circa 1960s, showing the staggered up and down platforms and signal cabin.

54323 GWR Garneddwen Halt General view, circa 1960s, showing the crossing loop.

54373 GWR Garneddwen Halt Detailed view showing Garneddwen Loop signal cabin.

57442 GWR Garneddwen Halt General view, circa 1960s, showing the staggered platforms and signal box.

54328 GWR Gilfach Postcard view, circa 1912, showing the single platform and station building.

54329 GWR Gilfach Postcard view, circa 1912, showing the single platform and station building.

52970 GWR Glan Llyn General view, circa 1960s, showing the single platform.

52971 GWR Glan Llyn General view, circa 1960s, showing the single platform.

54330 GWR Glanamman Post-closure view, circa 1960s, showing the level crossing and signal cabin.

54335 GWR Glanamman Post-closure view, circa 1960s, showing derelict facilities.

57918 GWR/LNWR Glanrhyd General view, circa 1960s, showing the single platform and station building.

57919 GWR/LNWR Glanrhyd General view, circa 1960s, showing the single platform and station building.

57920 GWR/LNWR Glanrhyd General view, circa 1960s, showing the single platform, station building and level crossing.

51967 GWR Glogue General view, circa 1962, showing the single platform, water tank and level crossing.

51968 GWR Glogue General view, circa 1962, showing the single platform and part of the station building.

57734 GWR Glogue General view, circa 1960, showing '45XX' class 2-6-2T taking water as it stands on the level crossing at the east end of the station.

57814 GWR Glyn Neath Postcard view, circa 1912, showing the up and down platforms, original wooden station buildings and standard GWR waiting room on the opposite platform.

57815 GWR Glyn Neath Post-closure view, circa 1960s, showing the up and down platforms and station buildings.

57816 GWR Glyn Neath General view, circa 1950s, showing '45XX' and '57XX' class locomotives outside motive power depot.

57817 GWR Glyn Neath General view, circa 1960s, showing the up and down platforms and station buildings.

57818 GWR Glyn Neath General view, circa 1960s, showing the up and down platforms and modernised station buildings.

57819 GWR Glyn Neath General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

57820 GWR Glyn Neath Detailed view, circa 1960s, showing the standard GWR hip-roofed signal cabin.

57360 GWR Grange Court General view, circa 1960, showing up and down main line platforms, station buildings and footbridge, looking west towards Fishguard.

57361 GWR Grange Court General view, circa 1960, showing up and down main line platforms and island station building, looking east towards Paddington.

57452 GWR Grange Court Postcard view, circa 1912, showing "Grange Court Station (West)".

57453 GWR Grange Court General view, circa 1960, showing up and down branch platforms and footbridge, looking east towards Paddington.

54334 GWR Groesffordd Halt General view, circa 1960s, showing the single platform and waiting shelter.

57859 GWR Hafodyrynys General view, circa 1960s, showing the up and down platforms and waiting shelter.

57860 GWR Hafodyrynys General view, circa 1960s, showing the up and down platforms.

52990 GWR Haverfordwest General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

57650 GWR Haverfordwest General view, 08-07-1965, showing the rear elevation of the main station building.

57651 GWR Haverfordwest General view, circa 1960, showing the up and down platforms, station buildings and footbridge.

57652 GWR Haverfordwest General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

57653 GWR Haverfordwest General view, circa 1960s, showing the up and down platforms, signal box and goods shed.

57843 GWR Hengoed Post-closure view, circa 1960s, showing the up and down platforms and standard GWR station buildings.

57844 GWR Hengoed Post-closure view, circa 1970, showing derelict facilities.

66364 GWR Hengoed General view of high level platforms, c1955, showing platforms from platform end with 4575 on autotrain.

57746 GWR Henllan General view, circa 1960s, showing the up and down platforms and station buildings.

57747 GWR Henllan General view, circa 1960s, showing the up and down platforms, station buildings and signal cabin.

57748 GWR Henllan View from overbridge, circa 1912, showing the up and down platforms, station buildings and goods shed.

66073 GWR Henllan General view, 26-8-48, looking down on platforms from overbridge.

57824 GWR Hirwaun Post-closure view, circa 1960s, showing the main station building.

57825 GWR Hirwaun Post-closure view, circa 1960s, showing the main station building.

57826 GWR Hirwaun Postcard view, circa 1912, showing the main up and down platforms and back platform road, main station building and island platform building.

57654 GWR Johnston General view, circa 1960, showing the up and down platforms, station buildings and footbridge.

57655 GWR Johnston General view, circa 1960, showing the up and down platforms and part of the station buildings.

57656 GWR Johnston General view, circa 1920, showing the up and down platforms, station buildings and footbridge.

57657 GWR Johnston General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

57658 GWR Johnston General view, circa 1960s, showing the up and down platforms and road overbridge.

51850 GWR Jordanston Halt General view, circa 1960, showing the waiting shelter.

57631 GWR Jordanston Halt General view, circa 1960, showing the waiting shelter.

51856 GWR Kidwelly General view, circa 1960s, showing the up and down platforms and road overbridge.

57582 GWR Kidwelly General view, circa 1920, showing the up and down platforms, station buildings and footbridge.

57583 GWR Kidwelly General view, circa 1963, showing the up and down platforms and station buildings.

57584 GWR Kidwelly General view, circa 1963, showing the up and down platforms and station buildings.

51957 GWR Kilgerran General view, circa 1962, showing the single platform and station building.

51958 GWR Kilgerran General view, circa 1962, showing the single platform and goods shed.

57737 GWR Kilgerran Postcard view, circa 1912, showing the single platform and goods yard, with timber being loaded.

57738 GWR Kilgerran General view, circa 1960s, showing the single platform and station building.

57673 GWR Kilgetty General view, circa 1960s, showing the single platform and station building, looking north towards Whitland.

57674 GWR Kilgetty General view, circa 1960s, showing the single platform and station building, looking south towards Pembroke Dock.

57675 GWR Kilgetty Archive view, circa 1912, showing the single platform and station building.

52937 GWR Lampeter General view, circa 1960s, showing the up and down platforms and station buildings.

52938 GWR Lampeter General view, circa 1960s, showing the up and down platforms, station buildings and signal box.

57795 GWR Lampeter Archive view, circa 1914, showing military personnel awaiting their train.

57796 GWR Lampeter Postcard view showing the platform crowded with horses during horse fair, 1904.

66071 GWR Lampeter General view, 6-48, showing platforms

57698 GWR Lamphey View from bridge circa 1950s, showing the single platform and station building, looking west towards Pembroke Dock.

57699 GWR Lamphey View west from bridge, circa 1920, showing the single platform, station building and cattle dock.

57700 GWR Lamphey Postcard view, circa 1912, showing steam railmotor alongside single platform.

57701 GWR Lamphey General view, circa 1960s, showing the single platform and adjacent good sidings, looking west towards Pembroke Dock.

57702 GWR Lamphey Postcard view, circa 1912, showing the single platform and station building, with approaching train.

57703 GWR Lamphey General view, circa 1960s, showing the single platform, goods siding and overbridge, looking east towards Whitland.

54371 GWR Lando Halt General view, circa 1960s, showing the up and down platforms and waiting shelter.

54372 GWR Lando Halt General view, circa 1960s, showing the up and down platforms, waiting shelter and footbridge.

54359 GWR Landore General view, circa 1960s, showing the platforms and station buildings.

54360 GWR Landore General view, circa 1960s, showing the platforms and station buildings.

57557 GWR Landore Low Level General view, circa 1963, looking towards Hafod Junction.

57558 GWR Landore Low Level General view, circa 1963, looking towards Felin Fran.

57559 GWR Landore Low Level General view, circa 1920, showing the single platform, station building and signal cabin.

57580 GWR/LNWR Lanfynydd Archive view, circa 1900, showing the station master and station garden.

57717 GWR Letterston Postcard view, circa 1912, showing the up and down platforms, station buildings and signal box.

57718 GWR Letterston General view, circa 1960s, showing the up and down platforms and station buildings.

57719 GWR Letterston General view, circa 1960s, showing the up and down platforms and station buildings.

54340 GWR Llandarcy General view, circa 1960s, showing the up and down platforms and road overbridge.

54355 GWR Llandarcy General view, circa 1960s, showing the up and down platforms.

52977 GWR Llandebie General view, circa 1960s, showing the single platform, station building and signal box.

52978 GWR Llandebie General view, circa 1960s, showing the single platform, looking towards the level crossing.

52979 GWR Llandebie Postcard view, circa 1912, showing the "Railway Station, LLandebie".

57923 GWR Llandilo General view, circa 1930s, showing the up and down platforms and station buildings.

57924 GWR Llandilo General view, circa 1960s, showing the up and down platforms and station buildings, with an unidentified '57XX' class 0-6-0PT.

57925 GWR Llandilo General view, circa 1960s, showing the up and down platforms, station buildings and signal box.

57926 GWR Llandilo General view, circa 1930s, showing the up and down platforms, station buildings and footbridge, looking north towards Craven Arms.

57927 GWR Llandilo General view, circa 1960s, showing the up and down platforms.

57928 GWR Llandilo General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

57929 GWR Llandilo General view, circa 1960s, showing the up and down platforms and station buildings.

57930 GWR Llandilo Detailed view, circa 1962, showing signal cabin.

66456 GWR Llandilo General view, c1955, looking to footbridge and canopies.

51842 GWR Llandilo Detailed view showing rear elevation of station building (07-07-1965).

36727 GWR Llandilo Archive view, c1910, showing LNWR Webb 2-4-2T piloting a 0-6-0 on a passenger train.

51853 GWR Llandilo Detailed view, c1955, showing ex-GWR 74xx 0-6-0PT 7402 bunker first at head of 2 coach local in main platform.

51854 GWR Llandilo General view, c1955, with Stanier 5MT 4-6-0 No. 45298 on southbound passenger.

51855 GWR Llandilo Panoramic view, c1910, looking down on station from hillside.

57044 GWR Llandogo Postcard view, circa 1930s, showing the single platform and shelter, looking towards Tintern (very similar to 57047).

57045 GWR Llandogo Post-closure view, circa 1960s, showing derelict facilities.

57046 GWR Llandogo Post-closure view, circa 1960s, showing derelict facilities.

57047 GWR Llandogo Postcard view, circa 1930s, showing the single platform and shelter (very similar to 57044).

13251 LNWR/GWR Llandovery Pre-Grouping view, circa 1912 (copy).

57922 GWR/LNWR Llandovery General view, circa 1963, showing the up and down platforms and station buildings.

57739 GWR Llandysill General view, circa 1960s, showing the up and down platforms and station buildings.

57740 GWR Llandysill General view, circa 1960s, showing the up and down platforms, station buildings and road overbridge.

57772 GWR Llandysill Postcard view, circa 1912, showing crowded scene, possibly on market day.

52950 GWR Llanelly General view, circa 1960s, showing the up and down platforms and station buildings.

54374 GWR Llanelly A detailed study of Llanelly East Signal Cabin, circa 1960s.

57522 GWR Llanelly General view, circa 1910, showing 4-4-0 No.3729 at the head of a main line passenger working.

57542 GWR Llanelly Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

57560 GWR Llanelly Postcard view, circa 1912, showing the up and down platforms, station buildings and water tower.

57561 GWR Llanelly View along platforms 2 & 3, circa 1960.

57562 GWR Llanelly Postcard view, circa 1912, showing the up and down platforms, station buildings and water tower.

66246 GWR Llanelly General view, 8-48, showing platforms from platform end with 4981 on mainline train and 3752 in bay.

54320 GWR Llanerch Halt Post-closure view, circa 1960s, showing derelict facilities.

51977 GWR Llanfalteg General view, circa 1962, showing brick building at south end of the single platform, looking north towards the level crossing.

51978 GWR Llanfalteg General view, circa 1962, showing the single platform, station building and level crossing, looking north towards Cardigan.

51979 GWR Llanfalteg General view, circa 1962, showing the single platform and station building, looking southwards from the level crossing.

57736 GWR Llanfrynach Postcard view, circa 1919, showing the single platform, station building and signal cabin from the level crossing.

51953 GWR Llanfrynach General view, circa 1962, showing the single platform and station building, looking northwards from the level crossing.

51969 GWR Llanfrynach General view, circa 1962, showing north end of single platform, looking towards the goods siding and cattle dock.

51980 GWR/LNWR Llangadock Postcard view, circa 1912, showing the up and down platforms and station buildings, looking towards the level crossing.

54351 GWR Llangadog General view, circa 1960s, showing the up and down platforms, station buildings and level crossing.

52980 GWR Llangeinor Postcard view, circa 1912, showing the station and surrounding hillsides.

52981 GWR Llangeinor Post-closure view, circa 1960s, showing derelict facilities.

52982 GWR Llangeinor General view, 01-04-1956, showing the up and down platforms and part of the station buildings.

54342 GWR Llangeinor General view, circa 1960s, showing the up and down platforms and level crossing with one track removed.

57896 GWR Llangennech General view, circa 1960s, showing the up and down platforms.

57897 GWR Llangennech General view, circa 1960s, showing the up and down platforms.

51972 GWR Llanglydwen General view, circa 1962, showing the up and down platforms, station buildings and level crossing.

51973 GWR Llanglydwen General view, circa 1962, showing the up and down platforms and station buildings.

51974 GWR Llanglydwen General view, circa 1962, showing the up and down platforms, station buildings and signal box.

57735 GWR Llanglydwen General view, circa 1960, showing level crossing and station building.

54348 GWR Llangower Halt General view, circa 1960s, showing the single platform and arc-roofed waiting shelter.

54339 GWR Llangynwydd General view, 01-04-1956, showing the up and down platforms and station buildings.

54349 GWR Llangynydd General view, circa 1960s, showing the up and down platforms with one track removed.

52975 GWR Llanybi General view, circa 1960s, showing the single platform and road overbridge.

52976 GWR Llanybi General view, circa 1960s, showing the single platform and road overbridge.

54353 GWR Llangynwyd General view, circa 1960s, showing the up and down platforms and station buildings.

54336 GWR Llangynwydd General view, circa 1960s, showing the up and down platforms, with one track removed.

54356 GWR Llanharan General view, circa 1960s, showing the up and down platforms and station buildings.

52984 GWR Llanharran Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

52985 GWR Llanharran Postcard view, circa 1912, showing the up and down platforms and station buildings.

52986 GWR Llanharran Postcard view, circa 1912, showing the up and down platforms and station buildings.

52987 GWR Llanharran General view, circa 1960s, showing the up and down platforms and footbridge.

54341 GWR Llanhilleth Post-closure view, circa 1960s, station the island platform and station building.

54343 GWR Llanhilleth Post-closure view, circa 1960s, station the island platform.

54352 GWR Llanhilleth Postcard view, circa 1912, showing "Llanhilleth from the Railway Station".

54354 GWR Llanhilleth Postcard view, circa 1912, showing "Station and Institute, Llanhilleth".

52939 GWR Llanilar General view, circa 1960s, showing the up and down platforms and station buildings.

52994 GWR Llanilar General view, circa 1960s, showing the up and down platforms, station buildings and signal cabin.

57870 GWR Llanilar General view, circa 1960s, showing the up and down platforms, looking south towards Carmarthen.

57871 GWR Llanilar Postcard view, circa 1912, showing the up and down platforms and station buildings, looking south towards Carmarthen.

57773 GWR Llanpumpsaint Panoramic view, circa 1906, showing the up and down platforms, station buildings and goods yard.

57774 GWR Llanpumpsaint Panoramic view, circa 1906, showing the up and down platforms, station buildings and goods yard, with goods train in crossing loop.

57775 GWR Llanpumpsaint General view, circa 1960s, showing the up and down platforms and part of the station buildings.

57776 GWR Llanpumpsaint General view, circa 1960s, showing the up and down platforms, station buildings and signal box.

57874 GWR Llanrhystyd Road Postcard view, circa 1912, showing the single platform, station building original signal box.

57875 GWR Llanrhystyd Road General view, circa 1960s, showing the single platform and signal cabin, looking north towards Aberystwyth.

57876 GWR Llanrhystyd Road General view, circa 1960s, showing the single platform and signal cabin.

57555 GWR Llansamlet Postcard view, circa 1912, showing the station from the adjacent road.

52947 GWR Llantarnum Post-closure view, circa 1960s, showing the derelict site.

52948 GWR Llantarnum Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

54357 GWR Llantarnum Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

57514 GWR Llantrisant General view, circa 1960, showing the main up and down platforms framed by bridge arch.

57515 GWR Llantrisant General view, circa 1960, showing the main up and down platforms and station buildings.

57516 GWR Llantrisant Platform end view, circa 1960s.

57517 GWR Llantrisant Postcard view, circa 1912, showing the "GWR Station Llantrisant".

57518 GWR Llantrisant View from footbridge, circa 1960, showing the main up and down platforms and station buildings.

57519 GWR Llantrisant Postcard view, circa 1912, showing "Llantrisant Station, GWR".

57520 GWR Llantrisant Postcard view, circa 1912, showing the main up and down platforms, station buildings and footbridge.

57521 GWR Llantrisant Postcard view, circa 1912, showing the platforms and station buildings from the footbridge.

57523 GWR Llantrisant Postcard view, circa 1912, showing the platforms and station buildings from the footbridge.

57524 GWR Llantrisant Postcard view, circa 1912, showing details of the station buildings.

57525 GWR Llantrisant Postcard view, circa 1912, showing "The Station, Llantrisant".

57526 GWR Llantrisant View from footbridge, circa 1912, showing the platforms and station buildings.

66143 GWR Llantrisant General view, 9-51, looking to station buildings from island platform.

52945 GWR Llanvihangel Post-closure view, circa 1960s, showing the signal cabin, station building and road overbridge.

52946 GWR Llanvihangel General view, circa 1960s, showing staggered platforms and road overbridge.

57942 GWR Llanvihangel Postcard view, circa 1912, showing the up and down platforms, road overbridge and part of the station buildings.

57497 GWR Llanwern Postcard view, circa 1912, showing the up and down platforms, station buildings and level crossing.

57498 GWR Llanwern Post-closure view, circa 1960s, showing derelict platforms and former station building.

57921 GWR/LNWR Llanwrda General view, circa 1965, showing the platform and station buildings.

57784 GWR Llanybyther General view, circa 1960s, showing the up and down platforms, looking north towards Aberystwyth.

57785 GWR Llanybyther General view, circa 1960s, showing the up and down platforms, station buildings and signal box, looking south towards Carmarthen.

57786 GWR Llanybyther General view, circa 1960s, showing the up and down platforms and signal box, looking north towards Aberystwyth.

52983 GWR Llanycefn Postcard view, circa 1912, showing the station and surrounding hillsides.

54347 GWR Llwydcoed Post-closure view, circa 1960s, showing abandoned site.

54350 GWR Llwydcoed Post-closure view, circa 1960s, showing derelict facilities.

51975 GWR Login General view, circa 1962, showing the single platform and station building, looking southwards from the level crossing.

51976 GWR Login General view, circa 1962, showing the single platform and station building, looking north towards the level crossing.

57554 GWR Loughor Post-closure view, circa 1960s, showing derelict facilities.

66478 GWR Lydney General view, 9-49, showing platforms and station building.

51851 GWR Lydstep General view of the single platform, circa 1960s.

51858 GWR Maesteg Castle Street General view, circa 1970s, showing the up and down platforms, station buildings and footbridge, with an unidentified class '37' visible in the distance.

51860 GWR Maesteg Castle Street Detailed view circa 1960s, showing the station buildings and concrete footbridge.

51863 GWR Maesteg Castle Street General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

51865 GWR Maesteg Castle Street General view, circa 1960s, showing the up and down platforms, station buildings and footbridge, with a single-car diesel unit in the station.

52879 GWR Maesteg Castle Street A detailed study of Maesteg Castle Street signal cabin.

52880 GWR Maesteg Castle Street General view, circa 1960s, showing the up and down platforms and station buildings, with the signal box visible beyond the footbridge.

52881 GWR Maesteg Castle Street Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

57779 GWR Maesycrugiau General view, circa 1960s, showing the up and down platforms and pagoda building, looking south towards Carmarthen.

57780 GWR Maesycrugiau General view, circa 1960s, showing the up and down platforms, station buildings and signal box, looking north towards Aberystwyth.

57781 GWR Maesycrugiau General view, circa 1950s, showing the up and down platforms, station buildings and signal box, looking north towards Aberystwyth.

57472 GWR Magor Postcard view, circa 1912, showing the up and down platforms, station buildings and signal box.

57473 GWR Magor View from the footbridge, circa 1960, showing the platforms.

57474 GWR Magor General view, circa 1960, showing the platform s , footbridge and road overbridge.

57475 GWR Magor Postcard view, circa 1912, showing the up and down platforms and station buildings.

57693 GWR Manorbier General view, circa 1960s, showing the up and down platforms and station buildings, looking west towards Pembroke Dock.

57694 GWR Manorbier General view, circa 1960s, showing the up and down platforms and station buildings, looking west towards Pembroke Dock.

57695 GWR Manorbier General view, circa 1950s, showing the up and down platforms and station buildings, looking east towards Whitland.

57696 GWR Manorbier General view, circa 1960s, showing the up and down platforms, station buildings and signal cabin, looking east towards Whitland.

57362 GWR Marshfield General view, circa 1963, showing the platform and station building.

57363 GWR Marshfield General view, circa 1963, showing the platform and station building.

52988 GWR Mathry Road General view, circa 1950s, showing the up and down platforms and station buildings.

52989 GWR Mathry Road General view, circa 1920s, showing staggered up and down platforms and station buildings.

57629 GWR Mathry Road General view, circa 1960, showing the up and down platforms and station buildings.

57630 GWR Mathry Road Postcard view, circa 1912, showing the up and down platforms and part of the station buildings.

57805 GWR Melyncourt Halt Post-closure view, circa 1970, showing derelict facilities.

57806 GWR Melyncourt Halt Post-closure view, circa 1970, showing derelict facilities.

57807 GWR Melyncourt Halt Postcard view, circa 1912, showing the up and down platforms and pagoda buildings, with steam railmotor No.7.

52925 GWR Merthyr General view, circa 1960s, looking towards the terminal buffer stops.

52926 GWR Merthyr Platform view, showing part of the station building, circa 1960s.

52927 GWR Merthyr General view, circa 1960s, showing the platform s .

52928 GWR Merthyr General view showing engine shed, circa 1950s.

66139 GWR Merthyr General view, 9-51, looking to train shed with pannier in the bay.

52925 GWR Merthyr General view, circa 1960s, looking to train shed with DMU in left hand platform..

52926 GWR Merthyr General view, circa 1960s, looking along platform under the canopy showing the station facility signs; track not visible.

52927 GWR Merthyr General view, circa 1960s, looking away from train shed with signal box in distance.

52928 GWR Merthyr Detailed view, circa 1950s, showing engine shed looking towards building and coaling stage with several panniers in view (poor focus)

57663 GWR Milford Haven General view, circa 1960, showing the platform and station buildings.

57664 GWR Milford Haven General view, 12-09-1963, showing the station building and goods shed.

57665 GWR Milford Haven General view, circa 1960s, showing the platform and signal box.

57666 GWR Milford Haven General view, circa 1960s, showing the single platform and station building.

66553 GWR Milford Haven, General view, circa 1953, looking along platform to station building.

66376 GWR Monmouth Troy General view, c1955, showing main building and canopies with auto train in platform.

66379 GWR Monmouth Troy Detailed view, c1955, showing 1421 being watered by tunnel mouth.

52958 GWR Morriston West General view, circa 1960s, showing the up and down platforms, station buildings and overbridge, looking towards Felin Fran.

52959 GWR Morriston West General view, circa 1960s, showing the up and down platforms and station buildings, looking towards Hafod Junction.

57828 GWR Mountain Ash View from train, circa 1963.

57829 GWR Mountain Ash Postcard view, circa 1912, showing "GWR Station Mountain Ash".

57830 GWR Mountain Ash Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

54363 GWR Nantyderry General view, circa 1960s, showing the up and down platforms.

54364 GWR Nantyderry General view, circa 1960s, showing the up and down platforms and road overbridge.

52873 GWR Nantylffyllon General view, circa 1960s, showing the up and down platforms.

52874 GWR Nantylffyllon Postcard view, circa 1912, showing the up and down platforms and station buildings.

52875 GWR Nantylffyllon Post-closure view, circa 1960s, showing the up and down platforms.

52876 GWR Nantylffyllon Postcard view, circa 1912, showing the up and down platforms and station buildings.

52826 GWR Nantylglo Post-closure view showing the derelict facilities.

52896 GWR Nantymoel Post-closure view, circa 1960s, showing derelict facilities.

52897 GWR Nantymoel Postcard view, circa 1912, showing the station and surrounding hillsides.

52898 GWR Nantymoel General view, circa 1960s, showing the single platform and station building, with railtour alongside.

52899 GWR Nantymoel Post-closure view, circa 1960s, showing derelict facilities.

52921 GWR Nantymoel General view, circa 1960s, showing the single platform and station building, with unidentified '94XX' class 0-6-0PT.

57667 GWR Narberth Postcard view, circa 1912, showing the up and down platforms, station buildings and goods shed, looking east towards Whitland.

57668 GWR Narberth General view, circa 1960s, showing the up and down platforms and part of the station buildings, looking south towards Pembroke Dock.

57669 GWR Narberth General view, circa 1960, showing the up and down platforms, station buildings and goods shed, looking east towards Whitland.

54366 GWR Neath Postcard view, circa 1912, showing the main up and down platforms and station buildings.

57489 GWR Neath General Detailed view, showing the rear elevation of the main station building, 06-07-1965.

57492 GWR Neath General General view, circa 1960, showing the platforms, part of the station buildings and footbridge.

57496 GWR Neath General General view, circa 1960, showing the up and down platforms and signal box.

57541 GWR Neath General General view, circa 1960, showing the up and down platforms, station buildings and footbridge.

66066 GWR Neath General General view, 8-48

57543 GWR Neath Low Level General view, circa 1912, showing the up and down platforms and station buildings, with steam railmotor.

66146 GWR Neath Riverside General view, 1951, taken from track level looking to platforms and footbridge after closure.

52992 GWR Nelson & Llancaiach Postcard view, circa 1912, showing the platforms and station buildings.

57837 GWR Nelson & Llancaiach Detailed view, 27-03-1955, showing the standard GWR station buildings.

57838 GWR Nelson & Llancaiach General view, circa 1960s, showing the main up and down platforms, part of the station buildings and footbridge.

57839 GWR Nelson & Llancaiach General view, circa 1960s, showing the main up and down platforms, island platform, station buildings and footbridge.

57840 GWR Nelson & Llancaiach General view, circa 1960s, showing the main up and down platforms, station buildings and lattice girder footbridge.

57841 GWR Nelson & Llancaiach Postcard view, 1912, showing the main up and down platforms, outer face of island platform and standard GWR station buildings.

57842 GWR Nelson & Llancaiach Detailed view, 27-03-1955, showing the rear elevation of the standard GWR station building and part of the lattice girder footbridge.

66453 GWR Nelson & Llancaiach General view, circa 1953, platforms and canopies from platform end.

54361 GWR New Passage Halt General view, circa 1960s, showing the single platform and road overbridge.

54362 GWR New Passage Halt View from bridge, circa 1960s, showing the single platform.

52853 GWR Newbridge Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

52854 GWR Newbridge Post-closure view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

52855 GWR Newbridge Postcard view, circa 1912, showing "Newbridge and Station".

52856 GWR Newbridge General view, circa 1962, showing the up and down platforms.

52857 GWR Newbridge Postcard view, circa 1912, showing the up and down platforms and surrounding hillsides.

57742 GWR Newcastle Emlyn General view, circa 1960s, showing the single platform and station building, looking west towards the terminal buffer stops.

57743 GWR Newcastle Emlyn General view, circa 1950s, showing the single platform and station building, looking west towards the buffer stops.

57744 GWR Newcastle Emlyn General view, circa 1960s, showing the single platform and station building, with '57XX' class 0-6-0PT No.9666.

57745 GWR Newcastle Emlyn General view, circa 1970s, looking east towards Pencader.

66074 GWR Newcastle Emlyn General view, 26-8-48, showing platform with 58xx on branch train; taken from goods yard

66082 GWR Newcastle Emlyn General view, 26-8-48, showing platform with 58xx on branch train; taken from track level at station throat.

66562 GWR Newcastle Emlyn, General view, 10-7-50, with 5819 on passenger train.

54368 GWR Newland Post-closure view, circa 1960s, showing derelict facilities.

57358 GWR Newnham General view, circa 1960, showing the up and down platforms, station buildings and footbridge, looking west towards Fishguard.

57359 GWR Newnham General view, circa 1960, showing the up and down platforms, part of the station buildings and road overbridge.

57456 GWR Newnham View from overbridge, circa 1912, showing the up and down platforms, station buildings and footbridge.

57457 GWR Newnham "Gloss Series" postcard view, circa 1912, showing the "GWR Station Newnham-on-Severn".

57458 GWR Newnham Postcard view, circa 1912, showing "Newnham-on-Seven The Station & Forest Railmotor".

57459 GWR Newnham Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge, looking east towards Paddington.

57460 GWR Newnham View from footbridge, circa 1912, showing the up and down platforms, goods shed and part of the station buildings.

57461 GWR Newnham Postcard view, circa 1923, showing the up and down platforms, station buildings and footbridge, looking east towards Paddington.

57462 GWR Newnham View from bridge, circa 1912, showing the up and down platforms and down passenger train.

66072 GWR Newnham General view, 1949, taken from platform end.

66415 GWR Newnham General view, 1949, showing platforms with 14XX in bay on Cinderford service.

54365 ADR Newport General view, circa 1960s, showing Newport Pill locomotive shed.

57487 GWR Newport Detailed view showing 'Castle' class 4-6-0 No.5005 *Manorbier Castle* piloting an unidentified 'Britannia' 4-6-2.

57488 GWR Newport General view, 12-07-1951, looking along Platform Five.

57490 GWR Newport General view, circa 1912, showing the platforms , part of the station buildings and Newport Middle signal cabin.

57491 GWR Newport Interior view of Newport Ebbw Junction shed, circa 1960, showing '57XX' class 0-6-0PTs Nos.4627, 4643 and 8705.

57493 GWR Newport General view, circa 1966, showing the platforms and station buildings.

57494 GWR Newport General view, circa 1960, showing the platforms 5 and 6.

57495 GWR Newport View along Platform Two, circa 1960.

66064 GWR Newport General view looking towards station from the west end, 1948

57659 GWR Neyland General view of goods yard, circa 1960s.

57660 GWR Neyland General view, circa 1930s, showing the station and sidings.

57661 GWR Neyland General view, circa 1960s, showing the platform and station buildings.

57662 GWR Neyland General view, circa 1960, showing the platform and station buildings.

66478 GWR Newyland General view, circa 1953, looking back along the platform to the buffers.

57882 GWR Nottage Halt General view, circa 1960s, showing the single platform.

57883 GWR Nottage Halt General view, circa 1960s, showing the single platform.

57450 GWR Oakle Street General view, circa 1960, showing the up and down platforms and part of the station buildings.

57451 GWR Oakle Street General view, circa 1960, showing the up and down platforms and station buildings.

64491 GWR Oakle Street General view, c1910, showing the up and down platforms and station buildings with station staff posed on platform (copy of postcard).

52900 GWR Ogmore Vale General view, circa 1960s, showing the up and down platforms and station buildings.

52901 GWR Ogmore Vale Detailed view showing Ogmore Vale South signal cabin.

52906 GWR Ogmore Vale General view, circa 1960s, showing the up and down platforms, station buildings and level crossing.

57863 GWR Olmarch Halt General view, circa 1960s, showing the single platform, waiting shelter and road overbridge, looking south towards Carmarthen.

57864 GWR Olmarch Halt General view, circa 1960s, showing the single platform and waiting shelter, looking north towards Aberystwyth.

52999 GWR Pandy General view, circa 1960s, showing the up and down platforms and station buildings.

54313 GWR Pandy General view, circa 1960s, showing the up and down platforms, station buildings and signal box.

54369 GWR Panteg & Griffithstown Postcard view, circa 1920, showing "Coedy-Gric Junction".

57968 GWR Panteg & Griffithstown Post-closure view, showing derelict facilities.

57969 GWR Panteg & Griffithstown Postcard view, circa 1912, showing the up and down platforms and station buildings.

57970 GWR Panteg & Griffithstown Postcard view, circa 1912, showing the up and down platforms and station buildings.

57971 GWR Panteg & Griffithstown Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

57972 GWR Panteg & Griffithstown Detailed view, circa 1962 showing Panteg & Coedycrig Junction signal cabin.

54367 GWR Panteg Works Postcard view, circa 1912, showing "Panteg Works Station".

57899 GWR Pantyffnon General view, circa 1960s, showing the main up and down platforms, branch platforms and station buildings.

57898 GWR Pantyffynnon General view, circa 1960s, showing the main up and down platforms and part of the station buildings.

57900 GWR Pantyffynnon General view, circa 1960s, showing the main up and down platforms, station buildings and footbridge.

57901 GWR Pantyffynnon General view, circa 1960s, showing branch platform and station buildings.

66458 GWR Pantyffynnon General view, 1955, taken from platform end looking to buildings and footbridge at far end of the platform

54325 GWR Pembrey General view, circa 1960s, showing the up and down platforms and road overbridge.

54326 GWR Pembrey View from bridge, circa 1912, showing the up and down platforms and station buildings.

66141 GWR Pembrey General view, 1951, looking to footbridge.

57704 GWR Pembroke General view, circa 1960s, showing the single platform and station building, looking west towards Pembroke Dock.

57705 GWR Pembroke General view, circa 1960s, looking east towards Whitland.

57706 GWR Pembroke General view, circa 1960s, showing the single platform, station building and goods lock-up, looking east towards Whitland.

57707 GWR Pembroke General view, circa 1960, showing the single platform and station building, looking west towards Pembroke Dock.

57708 GWR Pembroke Dock General view, circa 1960s, showing the up and down platforms and station buildings.

57709 GWR Pembroke Dock Postcard view, circa 1912, showing an unidentified 'Bulldog' class 4-4-0.

57710 GWR Pembroke Dock General view, circa 1960s, looking along the platform towards the station building.

57711 GWR Pembroke Dock Postcard view, circa 1912, showing the rear elevation of the main station building.

57712 GWR Pembroke Dock General view, 14-09-1962, showing the rear elevation of main station building.

57713 GWR Pembroke Dock General view, circa 1960s, showing the westernmost extremity of the passenger station.

57714 GWR Pembroke Dock General view, circa 1960s, looking east towards the signal box.

57715 GWR Pembroke Dock General view, 28-06-1955, showing the up and down platforms and station buildings, with '81XX' class 2-6-2T No.8107.

57716 GWR Pembroke Dock General view, circa 1960s, showing the up and down platforms and station buildings.

57974 GWR Pembrey & Burry Port General view, circa 1962, showing the up and down platforms and station buildings.

57690 GWR Penally General view, circa 1960s, showing the single platform and station building, looking south-west towards Pembroke Dock.

57691 GWR Penally Postcard view, circa 1912, showing the station, church and village.

57692 GWR Penally General view, circa 1960s, showing the single platform and station building, looking north-east towards Whitland.

57789 GWR Pencader General view, circa 1960s, showing the up and down platforms, station buildings and signal cabin.

57790 GWR Pencader General view, circa 1960s, showing the up and down platforms, with a '57XX' class 0-6-0PT in the down platform.

57791 GWR Pencader General view, circa 1960s, showing the up and down platforms, with 'Manor' class 4-6-0 No.7826 *Longworth Manor* and an unidentified '57XX' class 0-6-0PT.

57792 GWR Pencader General view, circa 1960s, showing the up and down platforms with BR class '2MT' 2-6-0 No.78000.

57793 GWR Pencader Postcard view, circa 1912, showing "Pencader Station from the Castle".

57794 GWR Pencader General view, circa 1960s, showing the up and down platforms, looking north towards Aberystwyth.

66075 GWR Pencader General view, 8-48, looking to footbridge showing platforms with signal prominent in foreground.

57865 GWR Pencarreg Halt General view, circa 1960s, showing the single platform, waiting shelter and overbridge, looking south towards Carmarthen.

57866 GWR Pencarreg Halt General view, circa 1960s, showing the single platform and waiting shelter, looking north towards Aberystwyth.

57527 GWR Pencoed View from footbridge, circa 1912, showing the up and down platforms and station buildings.

57528 GWR Pencoed General view, circa 1960, showing the up and down platforms and part of the station buildings.

57529 GWR Pencoed General view, circa 1960, showing the up and down platforms, station buildings and level crossing.

57973 GWR Penpergwm Post-closure view, showing derelict facilities.

57975 GWR Penpergwyn Post-closure view, showing derelict facilities.

57861 GWR Penrhiwceiber Panoramic view, circa 1912, showing GWR and TVR stations and the surrounding hillsides.

57862 TVR Penrhiwceiber Postcard view, circa 1912, showing "Station Approach, Penrhiwceiber".

57741 GWR Pentrecourt Halt Archive view, 01-02-1912, showing crowded platform and pagoda building.

54311 GWR Pentwynmawr Post-closure view, circa 1960s, showing derelict facilities.

54312 GWR Pentwynmawr Post-closure view, circa 1960s, showing derelict facilities.

52837 GWR Penygraig General view, circa 1960s, showing the up and down platforms and footbridge, with '14XX' class 0-4-2T No.1471 on auto-working.

52838 GWR Penygraig Post-closure view, circa 1960s, showing abandoned site.

52839 GWR Penygraig General view, circa 1960s, showing the up and down platforms and footbridge, with '14XX' class 0-4-2T No.1471.

52840 GWR Penygraig Panoramic view, circa 1912, showing the station, valley and Naval Colliery.

52841 GWR Penygraig Post-closure view, circa 1968, showing derelict facilities.

57405 GWR Peterchurch Post-closure view, circa 1970, showing derelict facilities.

57414 GWR Peterchurch Archive view, 1887, showing the single platform and station building, with ex-LNWR tank engine and 3-coach branch train.

57415 GWR Peterchurch Postcard view, circa 1912, showing the single platform and station building, with an unidentified '517' class 0-4-2T.

57417 GWR Peterchurch Postcard view, circa 1909, showing the single platform and station building, with adjacent church under repair.

52962 GWR Plas Marl Halt General view, circa 1960s, showing the level crossing, looking towards Felin Fran.

52963 GWR Plas Marl Halt View from the level crossing, circa 1960s, with an unidentified '57XX' class 0-6-0PT.

57572 GWR Plas Power Post-closure view, circa 1968, showing the up and down platforms.

57573 GWR Plas Power Postcard view, circa 1912, showing the up and down platforms and station buildings.

57574 GWR Plas Power Post-closure view, circa 1960s, showing derelict facilities.

57880 GWR Pont Llanio General view, circa 1960s, showing the up and down platforms, looking south towards Carmarthen.

57881 GWR Pont Llanio General view, circa 1960s, showing the single platform and station building, looking north towards Aberystwyth.

54315 GWR Pont Lliw Post-closure view, circa 1960s, showing the former station building (closed 1924).

54316 GWR Pont Lliw Post-closure view, circa 1960s, showing the former station building (closed 1924).

57902 GWR/LNWR Pontardulais General view, circa 1960, showing the platforms and part of the station buildings.

57903 GWR/LNWR Pontardulais A detailed view showing the entrance to the main station building.

57904 GWR/LNWR Pontardulais Platform view, circa 1960s, showing the footbridge and part of the station buildings.

57905 GWR/LNWR Pontardulais Postcard view, circa 1912, showing the "GW & LNWR Station, Pontardulais".

57906 GWR/LNWR Pontardulais General view, circa 1960s, showing the main up and down platforms.

57907 GWR/LNWR Pontardulais General view, circa 1960, showing the main up and down platforms and station buildings.

57908 GWR/LNWR Pontardulais General view, circa 1912, showing the LNWR and GWR platforms and station buildings.

66592 GWR/LNWR Pontardulais General view, circa 1956, showing platforms looking to footbridge with LMS 3F 47480 on enthusiasts special.

57845 GWR Pontllanfraith Low Level Postcard view, circa 1912, showing the up and down platforms and stone-built station buildings.

57846 GWR Pontllanfraith Low Level Postcard view, circa 1912, showing the up and down platforms from a nearby bridge.

57847 GWR Pontllanfraith Low Level Post-closure view, circa 1970, showing derelict facilities.

54304 GWR Pontnewydd Post-closure view, circa 1960s, showing derelict facilities.

54306 GWR Pontnewydd Post-closure view, circa 1960s, showing derelict facilities.

54308 GWR Pontnewydd Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

54309 GWR Pontnewydd Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

54310 GWR Pontnewydd Postcard view, circa 1912, showing the station building.

54314 GWR Pontnewydd Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

54337 GWR Pontnewydd Post-closure view, circa 1960s, showing derelict facilities.

52943 GWR Pontrilas Postcard view, circa 1912, showing the up and down platforms and station buildings.

57944 GWR Pontrilas General view, circa 1920, showing the up and down platforms and approaching train.

57945 GWR Pontrilas Postcard view, circa 1912, showing the station and surrounding scenery.

57946 GWR Pontrilas Postcard view, circa 1912, showing the up and down platforms and station buildings.

57947 GWR Pontrilas General view, circa 1960s, showing up platform and station buildings.

57948 GWR Pontrilas General view, circa 1960s, showing the platform and station buildings.

57949 GWR Pontrilas Panoramic view, circa 1912, showing the station and goods yard.

51859 GWR Pontycwmmmer Post-closure view, circa 1960s, showing the station building.

54305 GWR Pontycwmmmer Post-closure view, circa 1960s, showing derelict facilities.

57967 GWR Pontypool Blaendare Road General view, circa 1962, showing the up and down platforms and pagoda buildings.

57958 GWR Pontypool Clarence Street Post-closure view, circa 1968, showing the up and down platforms with tracks removed.

57959 GWR Pontypool Clarence Street General view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

57960 GWR Pontypool Clarence Street Postcard view, circa 1912, showing the up and down platforms, gothic station buildings and standard GWR plate girder footbridge.

57961 GWR Pontypool Clarence Street General view, 01-09-1953, showing the up and down platforms and gothic-style station buildings framed by footbridge.

57962 GWR Pontypool Clarence Street Post-closure view, circa 1960s, showing the up and down platforms and derelict station buildings.

57963 GWR Pontypool Clarence Street General view, 01-09-1953, showing the main station building from the station approach.

66452 GWR Pontypool Clarence Street General view, circa 1953, looking to footbridge from platform end.

57964 GWR Pontypool Crane Street General view, circa 1953, showing the up and down platforms, station buildings and footbridge.

57965 GWR Pontypool Crane Street General view, circa 1953, showing the station building framed by the footbridge.

57966 GWR Pontypool Crane Street Detailed view, 01-09-1953, showing the rear elevation of the main station building.

57950 GWR Pontypool Road Detailed view, 01-09-1953, showing the rear elevation of the main station building.

57951 GWR Pontypool Road Postcard view, circa 1912, showing "The Station, Pontypool Road".

57952 GWR Pontypool Road Archive view, circa 1900, showing the original Newport, Abergavenny & Hereford station buildings.

57953 GWR Pontypool Road Panoramic view, 31-08-1953.

57954 GWR Pontypool Road General view, circa 1960s, looking along main northbound platform from the southern end adjacent to the Bale of Neath bay.

57974 GWR Pontypool Road General view, circa 1962, showing the platforms and station buildings.

57955 GWR Pontypool Road General view, circa 1950s, showing details of the signalling, with the station visible in the background.

57956 GWR Pontypool Road

52907 GWR Pontyrhll Post-closure view, circa 1960s, showing derelict facilities.

52908 GWR Pontyrhll Postcard view, circa 1912, showing the single platform and station building.

52922 GWR Pontyrhll Post-closure view, circa 1960s, showing derelict facilities.

54302 GWR Pontywalby Halt Post-closure view, circa 1960s, showing derelict facilities.

54303 GWR Pontywalby Halt Post-closure view, circa 1960s, showing derelict facilities.

57544 GWR Port Talbot General view, circa 1960s, showing the modernised station buildings.

57545 GWR Port Talbot General view, circa 1960s, showing the modernised station.

57546 GWR Port Talbot General view, circa 1960s, showing the island platforms 1 & 2, and station buildings.

54321 GWR Porthcawl General view, circa 1960s, showing the north end of the platforms.

57884 GWR Porthcawl General view, circa 1960s, showing the up and down platforms station buildings

57885 GWR Porthcawl Detailed view, 19-07-1952, showing the main station building.

57886 GWR Porthcawl General view, circa 1960s, showing the platforms and station buildings, looking north towards Pyle.

57887 GWR Porthcawl Platform end view, 17-07-1952, looking north towards Pyle.

57888 GWR Porthcawl Postcard view, circa 1906, showing the original passenger station.

57889 GWR Porthcawl Detailed view, 17-07-1952, showing the rear elevation of the main station building.

57890 GWR Porthcawl Postcard view, circa 1918, showing the new station (opened 1916).

57891 GWR Porthcawl General view, circa 1960s, looking south towards the terminal buffer stops.

57892 GWR Porthcawl General view, circa 1960s, showing part of the station building, looking north towards the terminal buffer stops.

57893 GWR Porthcawl General view, circa 1960s, showing the platforms and station buildings, looking northwards from the rear of the buffer stops.

57471 GWR Portskewett Archive view, circa 1860, showing the original broad gauge station.

57499 GWR Portskewett Postcard view, circa 1912, showing the station approach and part of the station building.

57500 GWR Portskewett General view, circa 1960, showing the up and down platforms.

57501 GWR Portskewett Postcard view, circa 1912, showing the up and down platforms, station buildings and signal box.

57502 GWR Portskewett General view, circa 1960, showing the up and down platforms and part of the station buildings, framed by footbridge.

52949 GWR Pyle General view, 17-07-1953, showing the up and down platforms, station buildings and footbridge.

57533 GWR Pyle General view, circa 1963, showing the up and down platforms and footbridge, looking east towards Paddington.

57534 GWR Pyle General view, circa 1963, looking west towards Fishguard.

57535 GWR Pyle General view, circa 1963, showing the Porthcawl branch platforms and station buildings.

57536 GWR Pyle General view, circa 1963, showing the platforms and footbridge, looking west towards Fishguard.

66177 GWR Pyle General view, 1951, looking to branch platforms with 4404 in platform on branch train

66178 GWR Pyle General view, 1951, looking to mainline platforms and footbridge.

57831 GWR Quakers Yard High Level Post-closure view, circa 1960s, looking between platforms towards footbridge following removal of track.

57832 GWR Quakers Yard High Level Post-closure view, circa 1960s, looking between platforms from under footbridge following removal of track.

57831 GWR Quakers Yard High Level Post-closure view, circa 1960s, showing the up and down platforms and plate girder footbridge.

57832 GWR Quakers Yard High Level Post-closure view, circa 1970, showing derelict facilities.

66365 GWR Quakers Yard High Level Platform end view, circa 1955, showing 4575 being watered.

57808 GWR Resolven Postcard view, circa 1912, showing the up and down platforms, standard GWR station buildings and road overbridge.

57809 GWR Resolven Post-closure view, circa 1960s, showing the up and down platforms, station buildings and road overbridge.

57810 GWR Resolven Post-closure view, circa 1960s, showing the up and down platforms and part of the station building.

57811 GWR Resolven Postcard view, circa 1912, showing the up and down platforms, station buildings and road overbridge.

57812 GWR Resolven Postcard view, circa 1912, showing the up and down platforms, station buildings and steam railmotor No.7.

57813 GWR Resolven Detailed view, circa 1960s, showing Resolven West signal cabin.

57821 GWR Rhigos Halt Post-closure view, circa 1960s, showing the up and down platforms and road overbridge.

57822 GWR Rhigos Halt Post-closure view, circa 1970, showing derelict facilities.

57823 GWR Rhigos Halt Postcard view, circa 1912, showing the up and down platforms, pagoda buildings and arched stone overbridge.

54345 GWR Rhos Post-closure view, circa 1960s, looking towards Brook Street level crossing.

54346 GWR Rhos Post-closure view, circa 1960s, showing part of goods shed.

51970 GWR Rhydowen General view, circa 1962, showing the single platform and station building, looking north towards the level crossing.

51971 GWR Rhydowen General view, circa 1962, showing the single platform and station building.

52847 GWR Risca Postcard view, circa 1912, showing "The Railway Station Risca".

52848 GWR Risca Postcard view, circa 1912, showing "GWR Station, Risca, Mon".

52849 GWR Risca Post-closure view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

52850 GWR Risca Post-closure view, circa 1960s, showing the up and down platforms and footbridge.

52851 GWR Risca Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

52852 GWR Risca Post-closure view, circa 1960s, showing the up and down platforms, station buildings and footbridge.

54380 GWR Risca General view, circa 1960s, showing the platforms and station buildings.

54344 GWR Roath Postcard view, circa 1912, showing the up and down platforms station buildings and footbridge.

52845 GWR Rogerstone Post-closure view, circa 1960s, showing the up and down platforms signal box and part of the station buildings.

52846 GWR Rogerstone Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

54379 GWR Rogerstone General view, circa 1963.

57720 GWR Rosebush Archive view showing GWR staff group, circa 1910.

.

57601 GWR Sarnau General view, circa 1960, showing the up and down platforms and part of the station buildings, looking east towards Paddington.

57602 GWR Sarnau General view, circa 1960, showing the up and down platforms, part of the station buildings and level crossing, looking east towards Paddington.

51867 GWR Saundersfoot Archive view showing a train on the Saundersfoot Railway running along the main street.

57676 GWR Saundersfoot Postcard view, circa 1912, showing the up and down platforms and station buildings, looking south towards Pembroke Dock.

57677 GWR Saundersfoot General view, circa 1960, showing the up and down platforms and station buildings, looking south towards Pembroke Dock.

57678 GWR Saundersfoot General view, circa 1960s, showing the up and down platforms and part of the station buildings, looking south towards Pembroke Dock.

57476 GWR Severn Tunnel Junction General view, circa 1960, showing the platforms and footbridge.

57477 GWR Severn Tunnel Junction View from bridge, circa 1960s, showing the platform s , station buildings and footbridge.

57478 GWR Severn Tunnel Junction View from bridge, circa 1920s, showing the platforms and station buildings.

57479 GWR Severn Tunnel Junction Postcard view, circa 1912, showing the platforms and station buildings, with GWR staff group.

57480 GWR Severn Tunnel Junction General view, circa 1930, with approaching passenger train.

57481 GWR Severn Tunnel Junction General view, circa 1960, showing the platforms and signalling details.

57482 GWR Severn Tunnel Junction General view, circa 1960s, showing the platforms and station buildings.

57757 GWR Silian Halt Post-closure view, circa 1960s, showing the single platform.

57547 GWR Skewen General view, circa 1963, showing the up and down platforms and part of the station buildings.

57548 GWR Skewen Postcard view, circa 1912, showing the up and down platforms and station buildings.

57549 GWR Skewen General view, circa 1963, showing the up and down platforms.

57550 GWR Skewen Postcard view, circa 1912, showing the up and down platforms, station buildings and road overbridge.

57551 GWR Skewen Postcard view, circa 1912, showing the up and down platforms, station buildings and road overbridge.

57552 GWR Skewen General view, circa 1920, showing the up and down platforms and station buildings.

57603 GWR St Clears General view, circa 1960, showing the up and down platforms, looking east towards Paddington.

57604 GWR St Clears Archive view, 20-10-1904, showing horse-drawn vehicles assembled in the station yard.

57605 GWR St Clears General view, circa 1960, showing the up and down platforms, station buildings and goods shed.

57606 GWR St Clears General view, circa 1960, showing the up and down platforms and part of footbridge.

54381 GWR St Deveraux Postcard view, circa 1912, showing the up and down platforms and station buildings.

57943 GWR St Deveraux Post-closure view, showing former station building, circa 1968.

52790 GWR St Fagans Postcard view, circa 1912.

57511 GWR St Fagans Postcard view, circa 1912.

66144 GWR St Fagans General view, 9-51, looking along platforms to pagoda shelter with level cross in the distance.

57868 GWR Strata Florida General view, circa 1960s, showing the station buildings, looking south towards Carmarthen.

57869 GWR Strata Florida General view, circa 1960s, showing the up and down platforms, looking north towards Aberystwyth.

57566 GWR Swansea East Dock General view, circa 1912, with various private owner wagons in adjacent sidings.

57568 GWR Swansea East Dock Postcard view, circa 1912, looking towards the terminal buffer stops.

66541 GWR Swansea East Dock General view, 1956, showing disused platform and enthusiasts.

57564 GWR Swansea High Street General view, circa 1963.

57565 GWR Swansea High Street General view, circa 1963, looking towards the terminal buffer stops.

57567 GWR Swansea High Street Detailed view, circa 1900, showing Swansea High Street signal cabin.

57569 GWR Swansea High Street General view, 19-06-1964, showing the platforms and canopies, with an unidentified class '52' C-C.

57570 GWR Swansea High Street General view, 19-05-1964, showing an unidentified '94XX' class 0-6-0PT shunting empty coaching stock.

57607 GWR Swansea High Street General view, 07-09-1958, showing the rear elevation of the main station building.

57915 GWR/LNWR Talley Road Post-closure view, circa 1968, showing derelict facilities.

57916 GWR/LNWR Talley Road Post-closure view, circa 1968, showing derelict facilities.

52972 GWR Talsarn Halt General view, circa 1960s, showing the single platform.

57670 GWR Templeton Postcard view, circa 1912, showing the single platform, station building and signal cabin, looking north towards Whitland.

57671 GWR Templeton General view, circa 1960s, showing the up and down platforms and station buildings, looking north towards Whitland.

57672 GWR Templeton General view, circa 1960s, showing the up and down platforms and signal box, looking south towards Pembroke Dock.

57679 GWR Tenby General view, circa 1960s, showing the up and down platforms, station buildings and goods shed, looking south towards Pembroke Dock.

57680 GWR Tenby Postcard view, circa 1912, showing the up and down platforms and station buildings, looking north from the footbridge.

57681 GWR Tenby General view, circa 1960s, showing the up and down platforms, station buildings and water tower, looking south towards Pembroke Dock.

57682 GWR Tenby Postcard view, circa 1912, showing the up and down platforms and station buildings, looking south towards Pembroke Dock.

57683 GWR Tenby Detailed view, 06-07-1965, showing the rear elevation of the down side station buildings.

57684 GWR Tenby General view, circa 1960s, showing the up and down platforms, footbridge and goods shed, with 'Manor' class 4-6-0 No.7804 *Baydon Manor* on down passenger service.

57685 GWR Tenby General view, circa 1960, showing the up and down platforms, station buildings, goods shed and footbridge, looking north towards Whitland.

57686 GWR Tenby General view, circa 1960s, showing the up and down platforms, station buildings, looking south towards Pembroke Dock.

57687 GWR Tenby General view, circa 1960s, showing the up and down platforms, station buildings and footbridge, looking north towards Whitland.

57688 GWR Tenby General view, 06-05-1971, showing rear the elevation of the down side station buildings.

57689 GWR Tenby General view, circa 1958, showing the up and down platforms, station buildings and water tower, looking south towards Pembroke Dock.

66374 GWR Tintern General view, c1955, showing autotrain in platform from platform end

52882 GWR Tonde Postcard view, circa 1912, showing the up and down platforms and station buildings.

52883 GWR Tonde Postcard view, circa 1912, showing the up and down platforms, station buildings and footbridge.

52884 GWR Tonde Post-closure view, circa 1960s, showing the up and down platforms.

52885 GWR Tonde General view, circa 1970s, showing the up and down platforms and station buildings with one track removed.

52886 GWR Tonde General view, circa 1970s, showing the up and down platforms and station buildings, with unidentified class '37' Co-Co.

52887 GWR Tonde General view, circa 1970s, showing the up and down platforms with one track removed.

52888 GWR Tonde A detailed view of the engine shed, circa 1960s.

52889 GWR Tonde Postcard view, circa 1912, showing "GWR Junction, Tonde".

52890 GWR Tonde Postcard view, circa 1912, showing "GWR Junction, Tonde".

52891 GWR Tonde Postcard view, circa 1912, showing "Tonde Junction".

52892 GWR Tonde Postcard view, circa 1912, showing the up and down platforms and station buildings.

52893 GWR Tonde General view, circa 1960s, showing the up and down platforms and station buildings, with one track removed.

52894 GWR Tonde General view, circa 1960s, showing the up and down platforms and part of the station buildings, with one track removed.

66536 GWR Tonde General view, circa 1950, from track bed looking to platforms and vee of junction.

52842 GWR Tonyrefail Post-closure view, circa 1968, showing derelict facilities.

52843 GWR Tonyrefail Postcard view, circa 1912, showing the up and down platforms and station buildings.

52844 GWR Tonyrefail Postcard view, circa 1912, showing the up and down platforms and station buildings.

52944 GWR Tram Inn General view, circa 1960s, showing the level crossing and station buildings.

54301 GWR Tram Inn Detailed view showing Tram Inn signal cabin.

57941 GWR Tram Inn General view, circa 1950s, showing the staggered up and down platforms, station buildings and signal box.

57877 GWR Trawscoed Detailed view showing the signal cabin and station building, circa 1960s.

57879 GWR Trawscoed General view, circa 1960s, showing the single platform and station building, looking north towards Aberystwyth.

57872 GWR Tregaron General view, circa 1960s, showing the up and down platforms and station buildings, looking north towards Aberystwyth.

57873 GWR Tregaron General view, circa 1960s, showing the up and down platforms and part of the station buildings, looking south towards Carmarthen.

57878 GWR Tregaron General view, circa 1960s, showing the up and down platforms and station buildings, looking north towards Aberystwyth.

57833 GWR Treharris View from bridge, circa 1912, showing the up and down platforms and station buildings, with approaching train.

57834 GWR Treharris Postcard view, circa 1912, showing the up and down platforms, station buildings and road overbridge.

57835 GWR Treharris Post-closure view, circa 1970, showing derelict facilities.

57836 GWR Trelewis Halt General view, 23-03-1955, showing the up and down platforms and timber station buildings.

57848 GWR Treowen Halt Post-closure view, circa 1970, showing derelict facilities.

57849 GWR Treowen Halt Post-closure view, circa 1970, showing derelict facilities.

52923 GWR/RHYM Troedyrhiew Halt General view, circa 1960s, the showing the single platform.

52924 GWR/RHYM Troedyrhiew Halt General view, circa 1960s, showing the single platform.

57364 GWR Tutshill Halt General view, circa 1960, showing the up and down platforms and waiting shelters.

57365 GWR Tutshill Halt Post-closure view, circa 1967, showing the up and down platforms.

57996 GWR Tyllwyn Halt General view, circa 1964, showing the single platform.

57997 GWR Tyllwyn Halt General view, circa 1964, looking along the platform.

52955 GWR Tynycwm Halt General view, circa 1960s, station the island platform and waiting shelter.

52956 GWR Tynycwm Halt General view, circa 1960s, station the island platform and waiting shelter.

52957 GWR Tynycwm Halt General view, circa 1960s, station the island platform and waiting shelter.

57366 GWR Undy Halt View from bridge, circa 1960, showing the up and down platforms and waiting shelters.

57483 GWR Undy Halt General view, circa 1960, showing the up and down platforms and footbridge.

57484 GWR Undy Halt View from bridge, circa 1960, showing the up and down platforms and waiting shelters.

57994 GWR Victoria Halt Post-closure view, circa 1968, showing derelict facilities.

57995 GWR Victoria Halt Post-closure view, circa 1968, showing derelict facilities.

57412 GWR Vowchurch Postcard view, circa 1912, showing the single platform and station buildings, with station master Mr Pinnock.

57627 GWR Welsh Hook General view, circa 1960, showing the waiting shelters.

57628 GWR Welsh Hook General view, circa 1960, showing the waiting shelter.

57409 GWR Westbrook Post-closure view, circa 1970, showing the derelict facilities.

57410 GWR Westbrook Post-closure view, circa 1970, showing the derelict facilities.

57608 GWR Whitland General view, circa 1960, showing the up and down platforms, footbridge and level crossing, looking east towards Paddington.

57609 GWR Whitland Postcard view, circa 1912, showing down platform and goods shed.

57610 GWR Whitland Postcard view, circa 1912, looking westwards along the up platform.

57611 GWR Whitland View west from footbridge, circa 1914, showing up down platforms, station buildings and goods shed.

57612 GWR Whitland General view, circa 1919, showing the engine shed, with '1901' class 0-6-0PTs Nos.2012 and 1907.

57613 GWR Whitland General view, circa 1968, showing the up bay platform.

57614 GWR Whitland View west from the footbridge, circa 1912, showing the up side station buildings.

57615 GWR Whitland View west from footbridge, circa 1914, showing the up and down platforms, station buildings and goods shed.

66382 GWR Whitland Platform end general view, circa 1950s, looking to main station buildings with 45xx on branch train in loop platform; level crossing at far end of the station; soldier on platform no BR enamel signs

57625 GWR Wolfs Castle Halt General view, circa 1960, showing the up and down platforms and waiting shelters.

57626 GWR Wolfs Castle Halt General view, circa 1960, showing the up and down platforms, waiting shelter and road overbridge.